

Douglas Grafflin Elementary School, Chappaqua School District					
Sample Collection Date	Sample ID	Floor	Location	Lead Level (ppb)	Actions Taken
10/2/2020	001-Kitchen-KF-P-001	1	Kitchen, Pot filler 1	1680.00	Permanently removed from service. No further action required.
10/2/2020	01-Kitchen-KF-P-02	1	Kitchen, Pot filler 2	27.30	Permanently removed from service. No further action required.
10/2/2020	01-Kitchen-KF-P-03	1	Kitchen, Sink 3	6.83	Not Applicable
10/2/2020	01-Kitchen-KF-P-04	1	Kitchen, Sink 4	1.07	Not Applicable
10/2/2020	01-Kitchen-KF-P-05	1	Kitchen, Sink 5	ND	Not Applicable
10/2/2020	01-Kitchen-KF-P-06	1	Kitchen, Sink 6	ND	Not Applicable
10/2/2020	01-7-CF-P-01	1	Kindergarten 7, Sink 1	ND	Not Applicable
10/2/2020	01-6-CF-P-02	1	Kindergarten 6, Sink 2	ND	Not Applicable
10/2/2020	01-3-CF-P-03	1	Kindergarten 3, Sink 3	11.90	Not Applicable
10/2/2020	01-4-CF-P-04	1	Kindergarten 4, Sink 4	4.74	Not Applicable
10/2/2020	00-127-CF-P-05	Basement	CCW Sink 5	ND	Not Applicable
10/2/2020	00-120-CF-P-06	Basement	Classroom 120, Sink 6	ND	Not Applicable
10/2/2020	00-121-CF-P-07	Basement	Classroom 121, Sink 7	ND	Not Applicable



Douglas Grafflin Elementary School, Chappaqua School District					
Sample Collection Date	Sample ID	Floor	Location	Lead Level (ppb)	Actions Taken
10/2/2020	00-122-CF-P-08	Basement	Classroom 122, Sink 8	1.03	Not Applicable
10/2/2020	00-123-CF-P-09	Basement	Classroom 123, Sink 9	ND	Not Applicable
10/2/2020	02-220-CF-P-10	2	Classroom 220, Sink 10	ND	Not Applicable
10/2/2020	02-227-CF-P-11	2	Classroom 227, Sink 11	ND	Not Applicable
10/2/2020	02-221-CF-P-12	2	Classroom 221, Sink 12	ND	Not Applicable
10/2/2020	02-226-CF-P-13	2	Classroom 226, Sink 13	1.50	Not Applicable
10/2/2020	02-222-CF-P-14	2	Classroom 222, Sink 14	1.05	Not Applicable
10/2/2020	02-224-CF-P-15	2	Classroom 224, Sink 15	30.00	Removed and replaced the faucet. Confirmation sampling performed. See below.
10/2/2020	02-223-CF-P-16	2	Classroom 223, Sink 16	ND	Not Applicable
10/2/2020	01-Nurse-NS-P-1	1	Nurse's office, Sink 1	ND	Not Applicable
10/2/2020	00-105-CF-P-17	1	Classroom 105, Sink 17	ND	Not Applicable
10/2/2020	00-104-CF-P-18	1	Classroom 104, Sink 18	ND	Not Applicable
10/2/2020	00-103-CF-P-19	1	Classroom 103, Sink 19	ND	Not Applicable
10/2/2020	00-102-CF-P-20	1	Classroom 102, Sink 20	ND	Not Applicable



Douglas Grafflin Elementary School, Chappaqua School District					
Sample Collection Date	Sample ID	Floor	Location	Lead Level (ppb)	Actions Taken
10/2/2020	00-101-CF-P-21	1	Classroom 101, Sink 21	ND	Not Applicable
10/2/2020	00-111-CF-P-22	1	Classroom 111, Sink 22	ND	Not Applicable
10/2/2020	00-106-CF-P-23	1	Classroom 106, Sink 23	ND	Not Applicable
10/2/2020	02-211-CF-P-24	2	Classroom 211, Sink 24	1.36	Not Applicable
10/2/2020	02-206-CF-P-25	2	Classroom 206, Sink 25	1.81	Not Applicable
10/2/2020	02-205-CF-P-26	2	Classroom 205, Sink 26	3.48	Not Applicable
10/2/2020	02-204-CF-P-27	2	Classroom 204, Sink 27	ND	Not Applicable
10/2/2020	02-203-CF-P-28	2	Classroom 203, Sink 28	ND	Not Applicable
10/2/2020	02-208-CF-P-29	2	Classroom 208, Sink 29	ND	Not Applicable
10/2/2020	02-202-CF-P-30	2	Classroom 202, Sink 30	ND	Not Applicable
10/2/2020	02-201-CF-P-31	2	Classroom 201, Sink 31	3.51	Not Applicable
10/2/2020	Annex-A-CF-P-32	Annex	Annex A, Sink 32	1.73	Not Applicable
10/2/2020	Annex-B-CF-P-33	Annex	Annex B, Sink 33	1.35	Not Applicable
10/2/2020	Annex-Kitchen-KF-P-07	Annex	Kitchen, Sink 7	ND	Not Applicable



Lead Testing Results Table

Douglas Grafflin Elementary School, Chappaqua School District						
Sample Collection Date	Sample ID	Floor	Location	Lead Level (ppb)	Actions Taken	
Resample						
11/6/2020	02-224-CF-SSP-15	2	Classroom 224, Sink 15	51.50	Further flushing of new equipment performed. Confirmation sampling performed. See below.	
12/3/2020	02-224-CF-SSP-15	2	Classroom 224, Sink 15	ND	Not Applicable	

WSP USA, Inc. 96 Morton Street 8th Floor New York, NY 10014 wsp.com

Tel.: +1 212 612.7900